

Inspection Photos
Location Name: Reines 1-1H
Location ID: 427144



Photo 1 – Tank Battery Sign

Photo 2 – Tank Battery

Inspection Photos
Location Name: Reines 1-1H
Location ID: 427144



Photo 3 – Heater Treater

Photo 4 – Wellhead – Stained Soil

Inspection Photos
Location Name: Reines 1-1H
Location ID: 427144



Photo 5 – Stained Soil at Gas Engine

Photo 6 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Reines 1-1H
Location ID: 427144



Photo 7 – Stained Soil at Gas Engine

Photo 8 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Reines 1-1H
Location ID: 427144



Photo 9 – Stained Soil at Gas Engine

Photo 10 – Stained Soil West of Wellhead