


**Inspection Photos**  
**Location Name: 70 Ranch 4-63-3 Pad 2**  
**Location ID: 434077**



**Photo #1 Location**

**Inspection Photos**  
**Location Name: 70 Ranch 4-63-3 Pad 2**  
**Location ID: 434077**




**Photo #2 Mechanical Conditions**



**Photo #3 Stained Soil**



**Inspection Photos**  
**Location Name: 70 Ranch 4-63-3 Pad 2**  
**Location ID: 434077**




**Photo #4 Mechanical Conditions**



**Photo #5 Stained Soil**



**Inspection Photos**  
**Location Name: 70 Ranch 4-63-3 Pad 2**  
**Location ID: 434077**




**Photo #6 Mechanical Conditions**



**Photo #7 Stained Soil**



**Inspection Photos**  
**Location Name: 70 Ranch 4-63-3 Pad 2**  
**Location ID: 434077**




**Photo #8 Mechanical Conditions**




**Photo #9 Stained Soil**



**Inspection Photos**  
**Location Name: 70 Ranch 4-63-3 Pad 2**  
**Location ID: 434077**



**Photo #10 Mechanical Conditions**



**Photo #11 Stained Soil**