

# *Inspection Photos*

*Loc#334668*

*Operator: Caerus*

*Insp#:692403282*

*Insp Date: 4/7/21*





Photo#1:  
Overview of Location from entry.

April 7, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Scarber Loc#334669



Photo#2:  
Anchor and area of pad requiring maintenance.



Photo#3:  
Anchor in need of maintenance.

April 7, 2021



Photo#4:  
Interim area.

April 7, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#5:  
Interim area.

Caerus Scarber Loc#334669