

# *Inspection Photos*

*Loc#334667*

*Operator: Caerus*

*Insp#:692403285*

*Insp Date: 4/7/21*





Photo#1:  
Overview of Location from entry.

April 7, 2021



Photo#2:  
Degradation of pad surface.



Photo#3:  
Degradation of pad surface.

April 7, 2021



Photo#4:  
Fill slope vegetation.

April 7, 2021



Photo#5:  
Rocked drain at NE corner. Undercutting area  
marked with red