

Inspection Photos
Location Name: Wave 1H
Location ID: 430662



Photo 1 –Wellhead

Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: Wave 1H
Location ID: 430662



Photo 3 – Tank Battery

Photo 4 – Heater Treater

Inspection Photos
Location Name: Wave 1H
Location ID: 430662



Photo 5 – Gas Meter

Photo 6 – ECD and Flare

Inspection Photos
Location Name: Wave 1H
Location ID: 430662



Photo 7 – Stained Soil at Gas Engine

Photo 8 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 9 – Stained Soil at Gas Engine

Photo 10 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Wave 1H
Location ID: 430662



Photo 11 – Stained Soil at Gas Engine

Photo 12 – Flare base