


Karin Rhodes

From: Karin Rhodes
Sent: Wednesday, April 14, 2021 12:03 PM
To: g.richard.murray@state.co.us
Subject: JT Morris A 1 Well Tie - 688800875 Inspection

Mr. Murray,

In addition to the spill report with the root cause and corrective actions submitted March 25th, 2021 (which received closure), SIMCOE is responding to the pipeline integrity data request included in the inspection report for the JT Morris A1 wellsite, inspection number 402629451 (document number 688800875).

SIMCOE complies with the Flowline Integrity Management Regulation 1104.f. by using a continuous pressure monitoring program. A graph of the monitored pressure data is below, and the backup values are available.



Respectfully,
Karin Rhodes
SJNinspections@ikavenergy.com



IKAV Energy Inc
Karin Rhodes

Mobile: 970-769-1025
Email: krhodes@ikavenergy.com

1199 Main Ave
Suite 101
Durango, Colorado 81301, USA

Confidentiality notice:

This e-mail communication (and any attachment/s) are confidential and are intended only for the individual(s) or entity named above and to others who have been specifically authorized to receive it. Any information in this email and attachments may be legally privileged. If you are not the intended recipient, any disclosure, copying, reading, distribution, or any action taken or omitted in reliance on it, is prohibited and may be unlawful. Any opinions or advice contained in this email are subject to confidentiality and any terms and conditions may be protected by an engagement letter or other agreement. Please notify the sender that you have received this e-mail in error by calling the phone number above or by e-mail, and delete the e-mail (including any attachment/s) subsequently. This information may be subject to professional confidentiality (e.g. auditors, tax, or legal advisors), other privilege, or may otherwise be protected by work product immunity or other legal rules. Thank you.