

Inspection Photos
Location Name: Nielson #5
API: 05-007-06141



Nielson #5 location photo.



Nielson #5 well sign and pump jack. Well sign is not compliant with Rule 605.d.

Inspection Photos
Location Name: Nielson #5
API: 05-007-06141



Stained and wet well head and surroundings.



Free product around well head.

Inspection Photos
Location Name: Nielson #5
API: 05-007-06141



Nielson #5 well head with impacted soil and free product.



Nielson #5 crude oil AST. Tank battery sign is not compliant with Rule 605.e(2). Secondary containment does not appear to have adequate capacity.