

# *Inspection Photos*

*API#045-07273*

*Operator: Terra*

*Insp#:692403288*

*Insp Date: 4/9/21*





Photo#1:  
Overview of Location to Southeast.

April 9, 2021



Photo#2:  
View into Location along reclaimed access road.

April 9, 2021



Photo#3:  
BMPs at North end of site.



Photo#4:  
Area where maintenance is needed.

April 9, 2021