

Inspection Photos

Loc#323890

Operator: Terra

Insp#:692403289

Insp Date: 4/9/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Driving into Location.

April 9, 2021



Photo#2:
Overview of Location to West and entry.

April 9, 2021



Photo#3:
Debris at entry.

April 9, 2021



Photo#4:
Interim area.

Terra Barrett Loc#323890