

Inspection Photos

Loc#427211

Operator: Encana

Insp#:692403290

Insp Date: 4/9/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources




Photo#1:
Overview of Location from entry.

April 9, 2021



Photo#2:
Overview of Location to South.

April 9, 2021



Photo#3:
GE aerial view of Location 2016.

April 9, 2021



Photo#4:
View along East side berm.



Photo#5:
View along North berm.

April 9, 2021