

Inspection Photos
Location Name: VEGA USX /A03-05
Location #: 422947



Photo #1

Vega USX A03-05 (05-123-33459) Wellsite
Shut-In | SI



Photo #2

Vega USX A03-05 Battery site
Inactive | Shut-down.

Inspection Photos
Location Name: VEGA USX /A03-05
Location #: 422947



Colorado Oil & Gas Conservation Commission
Weld
+40.522355, -104.541089
172° S
13-Apr-2021 16:31

Photo #3
Vega USX A03-05 Battery site
Inactive | Shut-down.
Battery sign