

Inspection Photos
Location Name: LARAMIE ENERGY LLC BCU /13A Pad
Location ID: 311747



Photo #3466 from entrance to location.



Photo #3467 Battery sign weathered and not legible.

Inspection Photos

Location Name: LARAMIE ENERGY LLC BCU /13A Pad

Location ID: 311747



Photo #3468 Location lacks stabilization.



Photo #3469 Location lacks stabilization.

Inspection Photos

Location Name: LARAMIE ENERGY LLC BCU /13A Pad

Location ID: 311747



Photo #3470 No form of tracking control at entrance to location.