

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Bosely /SG 14-23

Location ID: 383331



Photo #3490 from entrance to location.



Photo #3139 from inspection #699802763 conducted on 3/15/21.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Bosely /SG 14-23

Location ID: 383331



Photo #3491 Location lacks stabilization.



Photo #3140 from inspection #699802763 conducted on 3/15/21.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Bosely /SG 14-23

Location ID: 383331



Photo #3492 Location lacks stabilization.



Photo #3141 from inspection #699802763 conducted on 3/15/21.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Bosely /SG 14-23

Location ID: 383331



Photo #3493 No form of tracking control at entrance to location.



Photo #3141 from inspection #699802763 conducted on 3/15/21.