WELLHEAD ABANDONMENT FORM

TASMAN GEOSCIENCES

SITE NAME: Rademacher 37-25		DATE: 4/14/2021	REM. PROJECT #: 16486	WEATHER: Cloudy 30 degrees
SITE DIRECTIONS: WCR 13 & WCR 28, W. 1/8, N. INTO		**CLIENT:** Oxy		
LEGALS AND LAT/LONG: 40.193497, -104.947231		**TASMAN PERSONNEL:** Sierra Kirylo		
SOIL TYPES: Clayey Sand - SC		**SURFACE GRADIENT:** South		

SOIL SAMPLING

Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?
4/14/2021 11:45	WH-B01@7'	1.0	Organic Content	No Odor	Yes	Lab
4/14/2021 11:46	WH-N01@5'	0.6	Organic Content	No Odor	Yes	N/A
4/14/2021 11:47	WH-S01@5'	0.6	Organic Content	No Odor	Yes	N/A
4/14/2021 11:48	WH-E01@5'	0.7	Organic Content	No Odor	Yes	N/A
4/14/2021 11:49	WH-W01@5'	0.4	Organic Content	No Odor	Yes	N/A
4/14/2021 11:50	WH-BG01@7'	0.3	Organic Content	No Odor	Yes	Lab
4/14/2021 11:51	WHS-N01@3"	0.6	Organic Content	No Odor	Yes	N/A
4/14/2021 11:52	WHS-S01@3"	0.4	Organic Content	No Odor	Yes	N/A
4/14/2021 11:53	WHS-E01@3"	0.4	Organic Content	No Odor	Yes	N/A
4/14/2021 11:54	WHS-W01@3"	0.6	Organic Content	No Odor	Yes	N/A

FACILITY INFRASTRUCTURE

EQUIPMENT	Quantity
Above Ground Storage Tank (AST)	
Buried or Partially Buried Vessel	
Separator	
Emission Control Device (ECD)	
Dump Line	
Wellhead	1
Flowline	
Other:	

Soil Loads Removed

IMPACTED SOIL IDENTIFIED?

ESTIMATED VOLUME OF IMPACTS:

Date	Number	CY
Total Removed	0	0

Disposal Facility:

Groundwater Recovery

DATE GW ENCOUNTERED: **DEPTH:**

GROUNDWATER IN CONTACT WITH IMPACTED SOIL?

LNAPL OR SHEEN OBSERVED ON GW?

Date	BBLS
Total Removed	0

Disposal Facility:

GROUNDWATER SAMPLING

Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?

TASMAN
GEOSCIENCES

Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:		Contents:	Material:	Volume:		Contents:
Notes/Conditions:				Notes/Conditions:			

Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:		Contents:	Material:	Volume:		Contents:
Notes/Conditions:				Notes/Conditions:			