

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /5NENE

Location ID: 334626



Photo #3524 from entrance to location.



Photo #3525 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /5NENE

Location ID: 334626



Photo #3526 Location lacks stabilization.



Photo #3527 Location lacks stabilization.



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /5NENE

Location ID: 334626



Photo #3528 No form of tracking control at entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources