

# *Inspection Photos*

*Loc#323994*

*Operator: Terra*

*Insp#: 692403311*

*Insp Date: 4/15/21*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overviews of Location.

April 15, 2021



Photo#2:  
Interim vegetation on SE slopes.



Photo#3:  
Interim vegetation on SE slopes.

April 15, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Insp Photos: Terra Savage Loc#323994