

Inspection Photos

API: 071-09252

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 4/19/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09252 | Date: 4/19/2021

Inspection Photos



Photo 1. Facing west toward the access road which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09252 | Date: 4/19/2021

Inspection Photos



Photo 2. Facing north along the access road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09252 | Date: 4/19/2021

Inspection Photos



Photo 3. Facing toward the fill slope of the road. There is sediment deposition in area shown at red arrow from erosion of the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09252 | Date: 4/19/2021

Inspection Photos



Photo 4. Facing north at the location which has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09252 | Date: 4/19/2021

Inspection Photos



Photo 5. Center of the location facing northwest.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09252 | Date: 4/19/2021

Inspection Photos



Photo 6. Facing toward the cut slope of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09252 | Date: 4/19/2021