

Inspection Photos
Location Name: Dunn 1-13H
Location ID: 426458



Photo 1 – Sign at Entrance



Photo 2 – Crude Oil Tanks – Capacity and Content Labels are fading



Inspection Photos
Location Name: Dunn 1-13H
Location ID: 426458



Photo 3 – H2O Tank – Capacity Label fading



Photo 4 – Tank Battery Sign



Inspection Photos
Location Name: Dunn 1-13H
Location ID: 426458



Photo 5 – Heater Treater



Photo 6 – ECD and Flare

Inspection Photos
Location Name: Dunn 1-13H
Location ID: 426458



Photo 7 – Wellhead



Photo 8 – Pumping Unit



Inspection Photos
Location Name: Dunn 1-13H
Location ID: 426458



Photo 9 – Wellhead Sign



Photo 10 – Exhaust – Stained Soil

Inspection Photos
Location Name: Dunn 1-13H
Location ID: 426458



Photo 11 – Stained Soil



Photo 12 – Gas Engine