

Inspection Photos  
Location Name: Federal 1-23  
Location ID: 312932



**Photo 1. Battery sign at separator not battery. Sign is incomplete/inaccurate.**



**Photo 2. Incomplete/inaccurate tank label.**

Inspection Photos  
Location Name: Federal 1-23  
Location ID: 312932



Photo 3. Sign at battery is incomplete/inaccurate.



Photo 4. Wellhead sign incomplete/inaccurate. No bradenhead access apparent.

