

Inspection Photos
Location Name: Hebron Central Facility
Location ID: 434014



Photo 1. Overview of location taken facing southwest.



Inspection Photos
Location Name: Hebron Central Facility
Location ID: 434014



Photo 2. Incomplete sign at location entrance.



Photo 3. Sign at battery incomplete.



Inspection Photos
Location Name: Hebron Central Facility
Location ID: 434014



Photo 4. Tank labels inaccurate.




Photo 5. Stained soil in tank battery.

