

Inspection Photos
Location Name: Woolley #1
Spill ID: 479484



Photo 1: Sign at entrance to Tank Battery on County Road



Inspection Photos
Location Name: Woolley #1
Spill ID: 479484



Photo 2: Excavation at release point.



Photo 3: Excavation of release and flowline repair.

Inspection Photos
Location Name: Woolley #1
Spill ID: 479484



Photo 4: Stockpiled material adjacent to excavation at release.



Photo 5: Excavation at flowline release. Water is presumed to be stormwater.