

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 20NENW
Location # 335458**



No battery sign at tank battery.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 20NENW
Location # 335458**



No battery sign at tank battery.



**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 20NENW
Location # 335458**



Location has been bladed.



**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 20NENW
Location # 335458**



Piece of 8" casing on edge of location.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 20NENW
Location # 335458**



**Unmarked deadman over north east edge
of location.**

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 20NENW
Location # 335458**



Uncompacted berm



Uncompacted berm

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 20NENW
Location # 335458**



Trash and debris bladed into uncompacted berm.



Trash and debris bladed into uncompacted berm.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 20NENW
Location # 335458**



Uncompacted berm.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 20NENW
Location # 335458**



North drain needs maintained.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 20NENW
Location # 335458**



Erosion channeling down path of location drainage.



Looking up to location drainage.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 20NENW
Location # 335458**



Erosion channeling down path of location drainage.