

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /30NWNW

Location ID: 334752



Photo #3555 from entrance to location.



Photo #3556 from entrance to location.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /30NWNW

Location ID: 334752



**Photo #3558 No battery sign located at the tank battery.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources