

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /29SESW

Location ID: 324346



Photo #3559 from entrance to location.



Photo #3560 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /29SESW

Location ID: 324346



Photo #3564 No battery sign located at the tank battery.



Photo #3561 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /29SESW

Location ID: 324346



Photo #3562 Location lacks stabilization.



Photo #3563 No form of tracking BMP at entrance to location.