

## Inspection Photos

**Location Name: TEP ROCKY MOUNTAIN LLC BOSELY-67S96W /23SESW**

**Location ID: 334579**



**Photo #3571 from entrance to location.**



**Photo #3572 from entrance to location.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY-67S96W /23SESW

Location ID: 334579



**Photo #3574 Location lacks stabilization.**



**Photo #3087 from inspection #699802725 conducted on 3/8/21.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY-67S96W /23SESW

Location ID: 334579



Photo #3575



Photo #3086 from inspection #699802725 conducted on 3/8/21.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY-67S96W /23SESW

Location ID: 334579



**Photo #3576 No form of tracking BMP located at entrance to location.**



**Photo #3089 from inspection #699802725 conducted on 3/8/21.**