

Inspection Photos

4/16/2021

Operator: TEP ROCKY MOUNTAIN LLC #
96850

Location ID: 334701
Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 334701



Photo 1: Photo taken from the south end of the Location, facing west. Photos 1-4 provide an overview of the Location from west, northwest, northeast to east.



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850
Location ID: 334701



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1. Photo also shows example of anchors observed marked on the Location.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 334701



Photo 5: Photo taken from the interim areas on the north end of the Location, facing west. Photo shows desirable perennial vegetative establishment is not progressing towards 1003 reclamation standards.



Photo 6: Photo taken from interim areas on the east end of the Location. Photo shows interim areas that do appear to be progressing towards 1003 standards.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 334701



Photo 7: Photo taken from the interim areas on the north end of the Location, facing west. Photos 7-10 provide an overview of the interim areas from west, northwest, northeast to east. Photos shows large areas of the interim where desirable perennial vegetative establishment is not progressing towards 1003 reclamation standards.



Photo 8: See comments under photo 7

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 334701



Photo 9: See comments under photo 7

Photo 10: See comments under photo 7