

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /19NESE

Location ID: 335031



Photo #3586 from entrance to location.



Photo #3587 from entrance to location.



Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /19NESE

Location ID: 335031



Photo #3588 Location lacks stabilization.



Photo #3589 location lacks stabilization.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /19NESE

Location ID: 335031




Photo #3590 No form of tracking BMP at entrance to location.



Photo #3591 No battery sign located at tank battery.