

Inspection Photos
Location Name: Waag Middle SENW Pad #1
Location ID: 439215



Photo 1: Wellhead Sign




Photo 2: Stained soil removed



Inspection Photos
Location Name: Waag Middle SENW Pad #1
Location ID: 439215



Photo 3: Wellhead Sign



Photo 4: Stained soil removed

Inspection Photos
Location Name: Waag Middle SENW Pad #1
Location ID: 439215



Photo 5: Stained soil removed



Photo 6: Wellhead Sign

Inspection Photos
Location Name: Waag Middle SENW Pad #1
Location ID: 439215



Photo 7: Stained soil



Photo 8: Stained soil