

Inspection Photos

API: 043-40014

Operator: JAVERNICK OIL

Inspection Date: 4/22/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-40014 | Date: 4/22/2021

Inspection Photos



Photo 1. Drone aerial image facing northeast along the access road. The road has not been recontoured and reclaimed. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40014 | Date: 4/22/2021

Inspection Photos



Photo 2. Facing northeast along the access road. The road the road continued to the left (arrow) and the well site was located at right (arrow). Reclamation has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40014 | Date: 4/22/2021

Inspection Photos



Photo 3. Facing back southwest at the location which is circled.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 043-40014 | Date: 4/22/2021

Inspection Photos



Photo 4. This former access road contuse to a PR well shown at red arrow. The road has not been reclaimed and is no longer used.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40014 | Date: 4/22/2021