

# *Inspection Photos*

*Loc#414152*

*Operator: Caerus*


*Insp#:692403326*

*Insp Date: 4/21/21*





Photo#1:  
Upper portion of Location that has been reclaimed.



Photo#2:  
View to lower pad and tank /separator pads.

April 21, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Rulison Loc#414152



Photo#3:

Overview of lower pad from entry. Showing ponding and rutting on east side of Pad & entry.

April 21, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Rulison Loc#414152



Photo#4:  
Debris on West side of well corral in traffic pattern.

April 21, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#5:  
Pad, East side of Well Corral.

Caerus Rulison Loc#414152



Photo#6:  
Snow melt off South rocked cut slope.



Photo#7:  
Snow melt off South rocked cut slope.

April 21, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Rulison Loc#414152



Photo#8:  
Lower level, separators.



Photo#9:  
Lower level, tanks.

April 21, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Rulison Loc#414152