

Inspection Photos

Location Name: LARAMIE ENERGY LLC NVega /4A

Location ID: 334463

Network time is not synchronized
Local: Apr 26, 2021 at 1:01:47 PM MDT



Photo #3620 from entrance to location.

Network time is not synchronized
Local: Apr 26, 2021 at 1:11:13 PM MDT



Photo #3621 Location lacks stabilization.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: LARAMIE ENERGY LLC NVega /4A

Location ID: 334463



Photo #3622 Location lacks stabilization.



Photo #3623 no form of tracking BMP.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources