

Inspection Photos
Location Name: Centennial 32-33
Location ID: 331747



Photo #1 Location

Inspection Photos
Location Name: Centennial 32-33
Location ID: 331747



Apr 28, 2021 at 9:40:26 AM
+40.3583, -104.4375
Weld

Colorado Oil & Gas Conservation Commission



Apr 28, 2021 at 9:45:27 AM
+40.3582, -104.4375
Weld

Colorado Oil & Gas Conservation Commission

Photo #2 Removed Stained soil

Photo #3 Removed Debris



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Centennial 32-33
Location ID: 331747




Photo #4 Appears to be a Leaking Regulator.



Photo #5 Oily waste