

# Inspection Photos

API: 071-09641

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/27/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09641 | Date: 4/27/2021

## Inspection Photos



**Photo 1.** Facing northwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09641 | Date: 4/27/2021

## Inspection Photos



**Photo 2.** Facing north toward the location. The vegetation is established in the interim area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09641 | Date: 4/27/2021

## Inspection Photos



**Photo 3.** Facing northwest toward the location. The vegetation is established in the interim area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09641 | Date: 4/27/2021