

Inspection Photos

4/27/2021

Operator: RIO MESA RESOURCES INC - 74740

Location ID: 314650

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 314650



Photo 1: Photo taken from the Location, facing south. Photo shows areas where work to remove stained soils was previously conducted. Photo shows requires stormwater and erosion control remain missing or insufficient. Unable to find evidence that seeding/revegetation activities have been performed.



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 314650



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1.

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 314650



Photo 5: Photo shows offsite sediment transport due to erosion degradation on the Location.



Photo 6: Photo shows areas where stained soils have not been removed.

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 314650



Photo 7: Photo shows areas where stained soils have not been removed.



Photo 8: Photo shows areas where stained soils have not been removed.

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 314650



Photo 9: Photo shows areas where stained soils have not been removed.

