

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/27/2021

Submitted Date:

04/29/2021

Document Number:

691201456**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Graber, Candice (Nikki) 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>
Knop, Max	303-825-4822	MKnop@kpk.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
477603	SPILL OR RELEASE	AC	08/10/2020		-	Peltier #2 Flowline	EI

**General Comment:**

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. No changes since previous inspections. Photos attached to document site conditions.



**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: No Form 19 or Form 27 has been submitted since 8/6/2020.Corrective Action: As per CA on Insp Document #691201366: Operator shall provide documentation of completed remedial actions within 45 days of the spill date. Supporting documentation shall include confirmation soil samples to document removal of impacts from soil in the release area and a site diagram that illustrates the release extent and location of confirmation soil samples.

Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691201457	Location Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5416254">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5416254</a>