

Inspection Photos
Suckla-Brown Unit 17 Header
Spill ID 478370 (AC)



Photo 1 – Spill area.



Photo 2 – Trash on location

Inspection Photos
Suckla-Brown Unit 17 Header
Spill ID 478370 (AC)



Photo 3 – Spill location and area disturbed from remediation.



Photo 4 – Disturbed area from spill remediation

Inspection Photos
Suckla-Brown Unit 17 Header
Spill ID 478370 (AC)



Photo 5 –Disturbed area from spill remediation



Photo 6 – Disturbed area from spill remediation