

Inspection Photos

Location Name: CAERUS PICEANCE LLC NAUROTH-68S96W /1SWNW

Location ID: 334125



Photo #3642 from entrance to location.



Photo #3643 from entrance to location.



Inspection Photos

Location Name: CAERUS PICEANCE LLC NAUROTH-68S96W /1SWNW

Location ID: 334125



Photo #3644 Location lacks stabilization.



Photo #3645 Location lacks stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC NAUROTH-68S96W /1SWNW

Location ID: 334125



Photo #3646 No form of Tracking BMP at entrance to location.