

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/30/2021

Submitted Date:

04/30/2021

Document Number:

699103516

FIELD INSPECTION FORMLoc ID 329316 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249346	WELL	TA	11/23/2020	OW	123-17148	JOHNSON 9-13	TA
422790	WELL	PR	08/01/2020	OW	123-33386	Mark Alter C16-79HN	PR
426538	WELL	PR	08/01/2020	OW	123-34721	ALTER C 16-28DX	TA
426540	WELL	PR	08/01/2020	OW	123-34722	ALTER C 16-29DX	TA
426541	WELL	SI	12/01/2020	OW	123-34723	ALTER C 09-24D	TA
426543	WELL	PR	08/01/2020	OW	123-34725	ALTER C 09-33D	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:		Date:	

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606	Date:	05/11/2021

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 6		
Comment:	Appear to be plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 249346 Type: WELL API Number: 123-17148 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: T/A

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/30/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 422790 Type: WELL API Number: 123-33386 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 08/01/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 426538 Type: WELL API Number: 123-34721 Status: PR Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: T/A

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/08/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: VAPOR

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 426540 Type: WELL API Number: 123-34722 Status: PR Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: T/A

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 04/13/2021Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 60Fluid Type: VAPOREnd Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 426541 Type: WELL API Number: 123-34723 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: T/A

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 04/06/2021Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 55Fluid Type: VAPOREnd Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 426543 Type: WELL API Number: 123-34725 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: T/A

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 03/31/2021Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 65Fluid Type: VAPOREnd Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Friday 4/30/21 at approximately 0828hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Mark Alter C 16-79HN of Noble Energy, at Location ID # 329753 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused Equipment needs to be removed for good housekeeping. Comply with Rule 606.</p> <p>With a corrective action date of 5/11/21.</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	04/30/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103517	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5418413