

**Inspection Photos**  
**Location Name: PO 12-12**  
**Location ID: 313081**



**Photo 1. Overview of location taken facing east.**



**Photo 2. Animal burrows in berm.**