

Inspection Photos
Location Name: Pronghorn 11-14-5HZ
Location ID: 427089



Photo 1 – Pumping Unit



Photo 2 – Tank Battery Signs



Inspection Photos
Location Name: Pronghorn 11-14-5HZ
Location ID: 427089



Photo 3 – Separators



Photo 4 – ECDs

Inspection Photos
Location Name: Pronghorn 11-14-5HZ
Location ID: 427089



Photo 5 – Tank Battery



Photo 6 – Riser Tag/Marked Missing

Inspection Photos
Location Name: Pronghorn 11-14-5HZ
Location ID: 427089



Photo 7 – 1" Riser STILL NOT Marked



Photo 8 – 1" Riser STILL NOT Marked

Inspection Photos
Location Name: Pronghorn 11-14-5HZ
Location ID: 427089



Photo 9 – Riser STILL NOT Marked



Photo 10 – Riser STILL NOT Marked



Inspection Photos
Location Name: Pronghorn 11-14-5HZ
Location ID: 427089



Photo 11 – Riser STILL NOT Marked



Photo 12 – Riser STILL NOT Marked

Inspection Photos
Location Name: Pronghorn 11-14-5HZ
Location ID: 427089



Photo 13 – Riser STILL NOT Marked




Photo 14 – Riser STILL NOT Marked



Inspection Photos
Location Name: Pronghorn 11-14-5HZ
Location ID: 427089




Photo 15 – Riser STILL NOT Marked




Photo 16 – Riser STILL NOT Marked