

Inspection Photos
Location Name: McCallum Unit 192
Location ID: 324737



Photo 1. Overview of location taken facing southeast.



Photo 2. No bradenhead access apparent.

