

Inspection Photos
Location Name: Ellgen 11-10-1
Location ID: 424294



Photo 1. Overview of location taken at entrance facing north.



Photo 2. Incomplete wellhead sign.



Inspection Photos
Location Name: Ellgen 11-10-1
Location ID: 424294



Photo 3. Incomplete tank battery sign.



Photo 4. Incomplete sign at entrance.

