

TEP
Jolley 1
Location # 335185



location



location

TEP
Jolley 1
Location # 335185



Location/Lack of stabilization/ compaction/tracking



Lack of stabilization/ compaction/tracking



TEP
Jolley 1
Location # 335185



Lack of stabilization/compaction/tracking



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
Jolley 1
Location # 335185



Lack of stabilization/erosion



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
Jolley 1
Location # 335185



Lack of stabilization/erosion



Ditch that is carrying sediment in following photos

TEP
Jolley 1
Location # 335185



Sediment migrating

TEP
Jolley 1
Location # 335185



Sediment migrating

**TEP
Jolley 1
Location # 335185**



**Previous inspection photo of lack of
stabilization/erosion**



**Follow up inspection photo of lack of
stabilization/erosion**



TEP
Jolley 1
Location # 335185



Previous inspection photo of lack of stabilization/erosion



Follow up inspection photo of lack of stabilization/erosion