

Inspection Photos
Location Name: Anne State 9-7
Location ID: 329904



Photo 1 – Wellhead



Photo 2 – Tank Battery Signs

Inspection Photos
Location Name: Anne State 9-7
Location ID: 329904



Photo 3 – Tank Battery



Photo 4 – H2O Tank now labeled

Inspection Photos
Location Name: Anne State 9-7
Location ID: 329904



Photo 5 – Gas Meter Shed and Separator



Photo 6 – Gas Meter Calibration Card NOT Present

Inspection Photos
Location Name: Anne State 9-7
Location ID: 329904



Photo 7 – NE Deadman NOT Marked



Photo 8 – SE Deadman NOT Marked