

**Inspection Photos**  
**Location Name: F Quarter Circle #1**  
**Location ID: 327148**



**Photo 1 – Tank Battery**



**Photo 2 – Tank Battery Signs**



**Inspection Photos**  
**Location Name: F Quarter Circle #1**  
**Location ID: 327148**



**Photo 3 – Pumping Unit**



**Photo 4 – Heater Treater**





**Inspection Photos**  
**Location Name: F Quarter Circle #1**  
**Location ID: 327148**



**Photo 5 – NFPA Label is fading**



**Photo 6 – Content Label is missing**



Inspection Photos  
Location Name: F Quarter Circle #1  
Location ID: 327148




Photo 7 – Calibration is overdue for Annual Calibration




Photo 8 – Stained Soil and Propane Labels Faded





**Inspection Photos**  
**Location Name: F Quarter Circle #1**  
**Location ID: 327148**



**Photo 9 – Stained Soil**



**Photo 10 – Wildlife Netting Missing on Containment**

