

**Inspection Photos**  
**Location Name: Gordon 1**  
**Location ID: 326779**



**Photo 1 – Wellhead – Unused Motor Valve, Chemical Tank and Stand**



**Photo 2 – Tank Battery Signs**

**Inspection Photos**  
**Location Name: Gordon 1**  
**Location ID: 326779**



**Photo 3 – Tank Battery – Weeds. Produced Water Content Label Fading**

**Photo 4 – Tank Battery - Weeds**



**Inspection Photos**  
**Location Name: Gordon 1**  
**Location ID: 326779**



**Photo 5 – Gas Meter Calibration Card missing**



**Photo 6 – Separator**

**Inspection Photos**  
**Location Name: Gordon 1**  
**Location ID: 326779**



**Photo 7 – Unmarked Riser at Separator**