



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**RGU 12-1-298 pad**  
**Inspection: 701500589**





**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Wells.**

**RGU 12-1-298 pad**  
**Inspection: 701500589**





39.90962, -108.34805, 6575.7ft, 54°  
05/04/2021 01:03:56 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Separator.**

**RGU 12-1-298 pad**  
**Inspection: 701500589**





39.90991, -108.34818, 6594.6ft, 82°  
05/04/2021 01:04:34 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 4. Tanks.**

**RGU 12-1-298 pad**  
**Inspection: 701500589**





39.91654, -108.34938, 6636.2ft, 134°  
05/04/2021 01:13:32 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 5. Plastic pipe trash along side of access road.**

**RGU 12-1-298 pad**  
**Inspection: 701500589**