

Waves 1H Photographs
Inspection Doc # 696303130
Loc ID 430662
API No. 123-36243



Stained soil at gas engine removed



Flare Stack base cleaned