

Reines 1-1H Photographs
Inspection Doc # 696303124
Loc ID 427144
API No. 123-34880



Stained soil at wellhead removed Stained soil at gas engine removed



Stained soil at gas engine removed



Stained soil at gas engine and west of wellhead removed