

Inspection Photos
Camenisch 1 sx Flowline Release
Spill ID 479713 (AC)



Colorado Oil and Gas Conservation Commission
40.07358, -104.86647, 4957.7ft, 12°
05/04/2021 09:54:39 AM

Photo 1 – Spill area. Fencing up around open excavation.



Colorado Oil and Gas Conservation Commission
40.0737, -104.86644, 4973.7ft, 16°
05/04/2021 09:55:15 AM

Photo 2 – Spill excavation. Impacts remain in situ. Side walls have collapsed into open excavation since last inspection.

Inspection Photos
Camenisch 1 sx Flowline Release
Spill ID 479713 (AC)



Photo 3 – Spill excavation.



Photo 4 – Additional disturbed area on site. Trash observed in disturbed area.

Inspection Photos
Camenisch 1 sx Flowline Release
Spill ID 479713 (AC)



Photo 5 – Soils stockpiled on location. Lining does not adequately protect surface soils. Trash remains on location.



Photo 6 – Soils stockpiled on location. Lining does not adequately protect surface soils.